


LS-4

ИЗОБРАЖЕНИЕ ИНСТРУМЕНТА



Список аксессуаров

x2	x1	x1	x1
x1	x12	x8	x4
x1	x1	x1	x8
x1			



Артикул	Габариты, мм	A(мм)
062028	900x1950	885-915
062029	1000x1950	985-1015
062030	1200x1950	1185-1215

